

NATIONAL RAILWAY

AR11

S/N No Data

EMD Aux. Generator Type 18KW

LOCOMOTIVE INBOUND INSPECTION REPORT

QF-10007 REV 1e

Model SD50 Road No. 5002 Frame No 847008-4 Sold To OEM Serial# Date Built Origin Inspector Briggs **Location Silvis** Date 9/20/2011 **BOTTOM INSPECTION** MU MU Hoses Front Short Nose Low Yes Yes **Dynamics** Yes Extended Grid(s) Condition Yes Good Bell Horn **Frame Condition** Yes Yes Good Fuel Tank Size 4500 (empty) **Retention Tank** Yes Condition Good Wheels L1 1 3/8 L4 1 3/4 2 1/8 R1 R4 SIZE L5 L2 2 1/4 1 11/16 R2 2 1/8 R5 1 3/4 L3 1 15/16 R6 L6 2 1/8 2 1/8 Box TYPE 4: Hyatt 1: Timken 2: Timken 5: Hyatt 6: Hyatt 3: Timken T.M. Type 1 **D87** 4 **D87** List cut / missing TM leads **NONE** 2 5 **D87 D87** Gear Ratio 62/16 Brake Shoe Type COMP. 3 **D87** 6 **D87** Axle Drive Type & Cond Draft Gear Type & Cond 390 Rear 390 Front Draft Gear Pocket Cond Front Good Rear Good **Coupler Type Front** Е Rear Е **Self-aligning Yes Condition Good Pilot Type Plate General Condition Bent / Damaged Plow Type Medium** Truck Type **HTC HTC Rigging Pin Type** Single **Single** High Brake Cyl. High LONGHOOD INSPECTION **Walkway Condition Good** Handrail Condition Good sides and rear/ front damaged Engine Type 16-645F3B 85B21012 EMD Block No (from A frame) 16F84K15 Bars Over Engine Overall Condition Good, but has oil leaks Internal / Bottom End Condition Good 06H9144TP Turbo P/N 8543498 S/N **Condition Good Diffusor Condition No access** Oil Cooler **Fuel Pump** PreHeater Yes Yes Starter Fuel Bypass Valve & Gage **Spark Arrestors** No **Exhaust Leaks** Yes Yes **Load Reguator Style** Spin On Filters Yes **Defect Tag** Yes Small **Radiators** Leaks? No Radiator Type Mech. Bond Fire Extinguishers: Longhood Yes Cab Yes AC Cabinet Yes Fan Fuses 200 Lb. Air Gauge Yes Yes Air Compressor Type Base Style Condition Air filter media type **Baggie** Air Brake Type/System **Condition Good** 26L **Condition Good** EMD Main Gen/Alt. Type S/N No Data

Condition Good



FANS D.B. Fan Qty. #1 Cool Fan Size 48 Blades Type 6 Fab #2 Cool Fan Size **Blades** Fab Type #3 Cool Fan 48 8 Size Blades Type Fab Equipment Rack Yes **Inertial Filters & Blower Motor** Yes No No Type Carbody Condition Good, but has some collision damage at front Paint Color/Condition Eng Room Grey / Dirty, Oily Carbody Green, Good Cab Gray / Dirty CAB/SHORT NOSE INSPECTION Cab Condtion Glass Meet FRA Reg **Condition Good** Floor Good Wall Good Yes **Cab Lights** Modules Air Brake change date 30-Jun Yes Yes # missing None H.V. Cabinet Wire Condition Good Wire Type **Exane** Magnetic Evidence of rewire? **Comments Nforce equipped** Yes Speedo Type Quantum Electric **Arm Rests** Yes **Heaters** Strip Seats Cab Cards Type Pulse **Event Recorder Equipped** Yes **Toilet Type Prime** Water Cooler Type Oasis Wipers Yes Visors Yes **Condition Good / Charged** Style 25 Plate **Batteries** Condition Good, but covers removed **Control Stand Type AAR** Alerter? Radio Equipment Yes EOT? Χ Cab Signal? **Computer Control?** ADDITIONAL DEFECTS/COMMENTS Stack not covered / water in turbo Rear crosswalk chain pull apart ring missing Front platform has colision damage Engine lube oil guage is wrong type (Main Resv.) Front Step wells have collision damage Guru plug assembly has been removed and plugged Front ditch light housings broken / mounts bent AR11 pit oily / dirty Front plow damaged / parts missing D14 pit oily / dirty / debris Short nose collision damaged / dented Engine room floors oily / dirty / corn / rags Front coupler bails collision damaged / bent Engine room sump oily / dirty / corn / debris Turbo expansion joint broken / major exhaust leakage Left front end sheet collision damaged / bent eft front mu hose mount broken Cab and engine room fire extinguishers are out of date Right front dummy MU receptacle collision damaged / broken Cab dirty / corn and debris on floor and in nose area Rear pilot plate damged / bent Rear conductors seat is removed / missing R1 wheel has over riding shoe All control stand covers removed R2 wheel has high / thin flange All mu hoses removed and placed in compressor room #3 wheels have flat and shelled areas Toilet need cleaned and serviced Hand brake wheel damaged / bent Engine has many oil leaks

Engine vee oily / dirty / debris

#5 TM cable clamp stud broken / clamp missing



All step wells stenciled "DO NOT BOARD"
Í
i e e e e e e e e e e e e e e e e e e e
<u>.</u>
(attach additional pages if needed)