				_					and Inspectio	n Rep
							Document	Control No.:	QF-10007	
	7						Release De	ocument :		
			MOVI	NG FC	RWA	RD	Revision: F	Rev 1		
Model	3GS21B	Road No.	NS 301	Frame No.	N/A	Sold To	NRF			
OEM Serial # (			2007		BUILT IN					
Inspector: T				Location:				Date:	5/26/2016	
·					INSPECT	ION				
Front:	Short		Nose:	Low		MU:	Yes		MU Hoses:	Yes
Dynamics:	No		Extended:	No		Grid(	s)Condition	: N/A		
Bell:	Yes		Horn:	Yes		Fram	e Condition	: GOOD		
Fuel Tank Size:			Reter	ntion Tank:	Yes		Condition	: GOOD		
Wheels:	L1	3	L4	## #####	R1	3	R4	2 7/8		
SIZE:	L2	## ####			R2	2 1/2	-		-	
	L3	2 7/8	·	······	R3	2 7/8	• 		<b>-</b>	
Box TYPE: H	yatt/Timk	en (H/T)								
1: H	2:		3:	т	2	4: T				
T.M. Type:	1	D78	4	D78	lis	t Cut/Missir	ng TM leads	: NONE		
	2	D78	5	2.0		o: 62/15	-	Shoe Type:	COMP	
	3	D78	6			Drive Type 8	-		RON / GOO	D
Draft Gear Type 8	2. Conditio	n:	Front:		390	,,	Rear		390	
Draft Gear Pocke			Front:		GOOD		- Rear		GOOD	
Coupler Type:	Front:	E	Rear:	E		elf-Aligning:	-	Condition:		חו
Pilot Type:	PLA			Condition:		ENT	103	Plow Type:		
Truck Type:	1	GP/B	2			g Pin Type:	-	1 SINGLE		SING
Brake Cyl.:	1	High	. –	2	High					
•				LONGHOO	D INSPEC	TION				
Walkway (	Condition:	GOOD			Handrai	Condition:	GOOD			
Engine Type: C	UMMINS	#1SN	37229679	#2SN	N 3722	9790	#3SN	37229812		
Engines Overall C	ondition:	GOOD			Internal/I	Bottom End	Condition:	N/A		
ENGINES P/N:	11000	1000	S/N:	SEE NOTES		Condition:	GOOD	Diffusor	Condition:	N/A
Fuel Pump:	Yes		PreHeater:	Yes		Oil Cooler:	Yes		Starter:	Yes
Fuel Bypass Valve	e & Gage:	No		Spark A	Arrestors:	No		Exh	aust Leaks:	No
Spin On Filt	ers:	Yes	L	.oad Regula	tor Style:	N/A		Def	fective Tag:	No
Radiators:	In	Leaks:	No	Radia	tor Type:			Mech	Bon	d
Fire Extinguishers	5:	Long	hood:	Yes		Cab:	Yes			
AC Cabinet:	N/A			F	an Fuses:	N/A	200Lb	. Air Gauge:	N/A	
Air Compressor T	ype:	ATLAS	Base S	Style:	STD.	Condition:	GOOD	SERIAL	WCF703039	9
Air Filter Type/Sy	stem:	994				Condition:	GOOD			
Air Filter Media T	ype:			Рар	er	Ot	ther			
Air Brake Type/S	/stem:	CCB26				Condition:	GOOD			
Main Gen/Alt. Ty	/pe:	N	RE			Condition:				
#1 GENSET	ID#	MG1	L0262	S/N:	058-0263	Condition:	GOOD			
#2 GENSET	ID#	MG1	10261	S/N:	058-0262	Condition:	GOOD			
#3 GENSET	ID#	MG1	L0388	S/N:	058-0267	Condition:	GOOD			
	.1 -		N//	4		Condition:				
A.G. Blower Whe	el Type:									

				/		Title: Locom	otive Inbou	ind Inspecti	on Repor
						Document C	Control No.:	QF-10007	
						Release Do	cument :		
		MOV	ING FO	<b>R</b> WA	RD	Revision: Re	ev 1		
		-							
Equipment Rack:	N/A	-		Inertial I	Filters & Blo	ower Motor:	N/A		
Carbody Condition:	VERY GOC	)D							
Paint Color/Contition:	Carbody:	BLACK / GOOD	D E	ng Room:	GREY/DIRTY		Cab:	GRREY/WOR	RN/DIRTY
			CAB/SHORT N	NOSE INSP	ECTION				
Cab Condition: Floo	r: GOOD	Wall: GOO	D G	ilass Meet	s FRA Req:	Yes	Condition:	GOOD	
Cab Lights: Yes	Modules	Yes	# Missing:	NONE		Air Brake Ch	ange Date:	11/6/2007	
H. V. Cabinet: Wire Cond	dition: GOOI	)	Wire Type:	Exane		Gear	Magnetic		
Evidence of Rewire?	Yes	Comments	S: RCL REMO	VED / ORP	HAN WIRI	NG IN HVC AI	ND SHORT I	NOSE	
Speedo Type: QUANTU	N	Heaters		Electric	Strip	Seats	3	Arm Rest:	Yes
Cab Cards YES	(If yes, rec	cord availab	le data)	Eve	ent Record	er Equipped:	Yes	Type:	QUANTUN
Toilet Type: MEI		Water C	Cooler Type:	N/A		Wipers:	YES	Visors:	4
Batteries: In		Condition	: DISCHARG	ED		Style:	18 PLATE		
Control Stand Type:	AAR					Condition:	GOOD		
Radio Equipment:	No		EOT:	No		Alerter:	Yes		
			Cab Signal:	No	Comp	uter Control	Yes		
L2 SPEEDO DRIVE MISSIN	G				· ·				
CANAC RCL EQUIPMENT F	REMOVED IN	NOSE AND	САВ						
#2 TRUCK BOLSTER RIDIN	G FAR BELO	W TRUCK FF	RAME / LEAF	SPRINGS I	NEARLY FLA	λΤ			
TOILET NEEDS SERVICE									
CAB AND LONG HOOD FIF	RE EXTINGUI	SHERS ARE	OUT OF DAT	E					
TRASH IN CAB AND SHOR	T NOSE ARE	۹S							
CAB ROOFTOP RCL BEACC	ONS MISSING	6							
CAB ROOFTOP RCL ANTEN	NNA MISSING	G							
COMPRESSOR ROOM DIR									
ENGINE ROOM FLOORS D									
CAB CONTROL STAND CO									
BATTERIES DISCHARGED /	NO POWER	TO CHECK	LIGHTS, ETC.						
WATER IN #1 AND #2 TM									
AIR CONDITIONER EQUIPI									
ELECTRIC HAND BRAKE EC									
FRONT AND REAR DITCH	-	PED							
N-FORCE EQUIPPED									

	Title: Locomotive Inbound Inspection Report				
	Document Control No.: QF-10007				
	Release Document :				
MOVING FORWARD	Revision: Rev 1				
(attach additional pages if needed)					