							Locomotiv	e Inbound Ir	nspection F	Report
			,	· · · · · ·		ľ		Control No.	-	•
	. ×			/			Release Do			
				NG FO		-	Revision: F			
			MOVI	NGFO	RWAR	D				
Model	SW/ 1500	Road No	NREX 350	Frame No.	72608-1	Sold To				
OEM Serial #	300 1300	Date Built	1973	Origin	72000-1	5010 10				
	BRIGGS/GF		1373	Location:		PADUCAH		Date	1/13/2016	
mspectori	5111005/01								1, 10, 2010	
Front:	LONG		Nose:	Low		MU:	NO	Ν	/U Hoses:	NO
Dynamics:	NO		Extended:	No		Grid(s	)Condition:		NA	
, Bell:	YES		Horn:	YES			Condition:		FAIR	
Fuel Tank Size:	600?		Reter	ntion Tank:	NO		Condition:			
Wheels:	L1	2 1/4	L4	2 1/4	R1	2 1/4	R4	2 1/2		
SIZE:	L2	2 1/2	L5	NA NA	R2	2 1/4	R5	NA		
0.22.	L3	2 1/2	L6	NA	R3	2 1/2	R6	NA		
Box TYPE:	TIM		_			· · ·	-			
1:T			3:	т	4:	т	5.1	N/A	6: N/	Δ
								-		
T.M. Type:	1 2	D77/78	4	D77/78		Cut/Missin 62:15	-			
	2	D77/78	5		Gear Ratio:			Shoe Type:	IRON	
	3	D77/78	6	NA	Axie D	rive Type &	Condition:		NA	
Draft Gear Type			Front:		485		Rear:		485	
Draft Gear Pocl	ket Conditio	on:	Front:		FAIR		Rear:		FAIR	
Coupler Type:	Front:	E	Rear:		Se	If-Aligning:	NO	Condition:	FAIR	
<i>·</i> ··	PLATE		General	Condition:	BEI		Plow Type:	-	PLAT	E
Truck Type:	1		2			g Pin Type:	1	clip	2 <u>c</u>	lip
Brake Cyl.:	1	High		2	High					
	<b>a</b> 11-1		=	LONGHOO	DD INSPECT					
-	Condition:		FAIR			Condition:	4057014	FAIF		
Engine Type:			73-L1-1030	- EMD BIO	ck No. (from			Bars Over:	NO	
GE Engines:	Block#:		H'Number:			Japstar	Anleister	BCI	Other:	
Engine Overall		Δ	FAIR		Internal/Bot	Condition:	ondition:	OK	Condition:	
Turbo P/N: Fuel Pump:	Yes	A	S/N: PreHeater:	YES		Oil Cooler:	Yes	-	Starter:	NO
Fuel Bypass Val			Fieneatei.		Arrestors:	NO	163		ust Leaks:	NO
Spin On F		YES			lator Style:				ective Tag:	NO
Radiators:	IN IN	Leaks:		-	-		DLDER		clive lag.	NU
Fire Extinguishe			hood:	YES	iator Type:	Cab:	YES	RS-MECH		
AC Cabinet:	NO	LUIIg	1000.	TES	Fan Fuses:	NO		Air Gauge:	NO	
Ac Cabinet: Air Compressor		WBO	Base S	Style		Condition:	FAIR	An Jauge:		
-		****	Dases			Condition:				
Air Filter Type/System: Condition:   Air Filter Media Type: BAGGIE										
Air Braker Type			2	6L		Condition:		FAIR TO I		
EMD Main Gen	-		2 32B		73-L1-1070	-		FAIR TO FAIR		
EMD Aux. Gene			KW			Condition:		FAIF		
	Model:	10	1			Condition:		I AIF	۱	
	Model:					Condition:				
GE EACHEN.	Widdel.			5/14.		condition.				

							Locomotiv	e Inbound	Inspection	Repor
								Control No	-	-
				/	7		Release De	ocument :		
			MOVI	NG FO	RWAR	D	Revision:	Rev 1		
A.G. Blower Whe	el Type:				(	Condition:				
D.B. Fan:	Qty:		Size		Blades:		Туре		Fab	
<pre>#1 Cool Fan:</pre>	Size:	48	Blades	: 10	Type:	FAB			GE, ALCO	
#2 Cool Fan:	Size:		Blades		Type:			Fa	an Drive Typ	e
#3 Cool Fan:	Size:		Blades		Type:			Eddy Cu	irrent Dire	ct Drive
#4 Cool Fan:	Size:		Blades		Type:			Condition:		
Equipment Rack:		YES	Туре		Inertial Fi	ters & Blo	wer Motor	NO		
Carbody Conditio	n:	GOOD								
Paint Color/Conti	ition:	Carbody:	Blue - Fade	C	Eng Room: (	GRAY - OIL	(	Cab:	GRAY-WO	RN
			C	CAB/SHORT I	NOSE INSPEC	TION				
Cab Condition:	Floor:	FAIR	Wall: Fair		Glass Meets	FRA Req:	YES	Condition	: OK	
Cab Lights:	YES	Modules	NO	# Missing:		4	Air Brake Ch	ange Date:		
H. V. Cabinet:	YE	ES		Wire Type:		EXANE	Gear	Magnetic		
Evidence of Rewi	re?	YES	Comments	:						
Speedo Type: N	ONE		Heaters		WATER		Seats	1EA	Arm Rest:	NO
Cab Cards N					Ever	nt Recorde	r Equipped	NO	Туре:	
<b>Foilet Type:</b> N	ONE		Water C	ooler Type:	NONE		Wipers:	YES	Visors:	NONE
Batteries:	IN		Condition				•	: 18 PLATE		
Control Stand Typ		AAR					Condition:			
Radio Equipment		NO		EOT:	NO		Alerter:		NO	
				Cab Signal:	NO	Compi	iter Contro	I NO		
						p-				
				HASLOW PR						
				HAS LOW PR			TE			
			EQUIP W	HAS LOW PR V/ HOT STAR ALL WHEELS	T AND CATT	RON REMO	TE			
			EQUIP W	V/ HOT STAR	T AND CATTE HAVE ROOL	RON REMO OVER	TE			
			EQUIP W	V/ HOT STAR ALL WHEELS ACT DAMAGE	T AND CATTE HAVE ROOL	RON REMO OVER TEPSKIRT	TE			
			EQUIP W	V/ HOT STAR ALL WHEELS ACT DAMAGE	T AND CATTF HAVE ROOL E LS FRONT S DOOR MISSI	RON REMO OVER TEPSKIRT NG	TE			
			EQUIP W	V/ HOT STAR ALL WHEELS ACT DAMAGE REAR HVC REMOTE LITE	T AND CATTF HAVE ROOL E LS FRONT S DOOR MISSI	RON REMO OVER TEPSKIRT NG SSING	TE			
			EQUIP W	V/ HOT STAR ALL WHEELS ACT DAMAGE REAR HVC REMOTE LITE	T AND CATTF HAVE ROOL E LS FRONT S DOOR MISSI E GLOBES MIS	RON REMO OVER TEPSKIRT NG SSING	TE			
			EQUIP W	V/ HOT STAR ALL WHEELS ACT DAMAGE REAR HVC REMOTE LITE	T AND CATTF HAVE ROOL E LS FRONT S DOOR MISSI E GLOBES MIS	RON REMO OVER TEPSKIRT NG SSING	TE			
			EQUIP W	V/ HOT STAR ALL WHEELS ACT DAMAGE REAR HVC REMOTE LITE	T AND CATTF HAVE ROOL E LS FRONT S DOOR MISSI E GLOBES MIS	RON REMO OVER TEPSKIRT NG SSING	TE			
			EQUIP W	V/ HOT STAR ALL WHEELS ACT DAMAGE REAR HVC REMOTE LITE	T AND CATTF HAVE ROOL E LS FRONT S DOOR MISSI E GLOBES MIS	RON REMO OVER TEPSKIRT NG SSING	TE			
			EQUIP W	V/ HOT STAR ALL WHEELS ACT DAMAGE REAR HVC REMOTE LITE	T AND CATTF HAVE ROOL E LS FRONT S DOOR MISSI E GLOBES MIS	RON REMO OVER TEPSKIRT NG SSING	TE			
			EQUIP W	V/ HOT STAR ALL WHEELS ACT DAMAGE REAR HVC REMOTE LITE	T AND CATTF HAVE ROOL E LS FRONT S DOOR MISSI E GLOBES MIS	RON REMO OVER TEPSKIRT NG SSING	TE			
			EQUIP W	V/ HOT STAR ALL WHEELS ACT DAMAGE REAR HVC REMOTE LITE	T AND CATTF HAVE ROOL E LS FRONT S DOOR MISSI E GLOBES MIS	RON REMO OVER TEPSKIRT NG SSING	TE			
			EQUIP W	V/ HOT STAR ALL WHEELS ACT DAMAGE REAR HVC REMOTE LITE	T AND CATTF HAVE ROOL E LS FRONT S DOOR MISSI E GLOBES MIS	RON REMO OVER TEPSKIRT NG SSING	TE			
			EQUIP W	V/ HOT STAR ALL WHEELS ACT DAMAGE REAR HVC REMOTE LITE	T AND CATTF HAVE ROOL E LS FRONT S DOOR MISSI E GLOBES MIS	RON REMO OVER TEPSKIRT NG SSING	TE			
			EQUIP W	V/ HOT STAR ALL WHEELS ACT DAMAGE REAR HVC REMOTE LITE	T AND CATTF HAVE ROOL E LS FRONT S DOOR MISSI E GLOBES MIS	RON REMO OVER TEPSKIRT NG SSING	TE			
			EQUIP W	V/ HOT STAR ALL WHEELS ACT DAMAGE REAR HVC REMOTE LITE	T AND CATTF HAVE ROOL E LS FRONT S DOOR MISSI E GLOBES MIS	RON REMO OVER TEPSKIRT NG SSING	TE			
			EQUIP W	V/ HOT STAR ALL WHEELS ACT DAMAGE REAR HVC REMOTE LITE	T AND CATTF HAVE ROOL E LS FRONT S DOOR MISSI E GLOBES MIS	RON REMO OVER TEPSKIRT NG SSING	TE			
			EQUIP W	V/ HOT STAR ALL WHEELS ACT DAMAGE REAR HVC REMOTE LITE	T AND CATTF HAVE ROOL E LS FRONT S DOOR MISSI E GLOBES MIS	RON REMO OVER TEPSKIRT NG SSING	TE			

	Locomotive Inbound Inspection Report				
	Document Control No.: QF-10007				
	Release Document :				
MOVING FORWARD	Revision: Rev 1				
(attach additional pages if needed					
	1				